

TOP SECRET 290918Z APR 71 CITE [REDACTED]

25X1

25X1 IMMEDIATE [REDACTED] INFO IMMEDIATE [REDACTED]

25X1

[REDACTED]
COMMANDERS SUMMARY, MISSION C-111-C

25X1

FOR GENERAL KNOWLES

25X1 1. MISSION GENERATION: PREPARATION OF AIRCRAFT AND
SYSTEMS WAS ROUTINE WITH NO PROBLEMS.

25X1
25X1

PAGE 2 T O P S E C R E T

5. LANDING PHASE: THE BRAKES FAILED DURING LANDING ROLL OUT. AIRCRAFT WAS STOPPED WITH NO DIFFICULTY. PRELIMINARY INVESTIGATION INDICATES FAILURE OF THE BRAKE FLANGE.

6. DEBRIEFING COMMENTS:

A. AIRCRAFT AND SYSTEMS: BRAKE FAILURE DURING LANDING ROLL. AVIONICS SYSTEMS O.K.

B. INTELL: NO SIGNIFICANT SIGHTINGS.

C. WEATHER: WEATHER IN TARGET AREA WORSE THAN FORECAST. PT. G TO PT. H: CAT V, PT. H TO PT. I: CAT III TO CAT IV, PT. I TO PT. J: CAT V, PT. J TO PT. L: CAT IV, PT. L TO PT. O: -5 888, PT. O TO PT. R: CAT I; PT. R TO PT. T: CAT IV, PT. T TO PT. W: CAT IV TO V.

D. CAMERA: OPERATION OK, 3,006 CYCLES AND 1252 FEET OF FILM USED.

E. PILOT COMMENTS: ALTHOUGH WEATHER BETWEEN PT. R AND PT. T WAS CAT IV THE PILOT BELIEVES THAT

25X1

PAGE 3 T O P S E C R E T

PHOTOGRAPHIC COVERAGE OF THE PRIMARY TARGET WAS
OBTAINED.

7. ESTIMATE OF MISSION SUCCESS: ESTIMATE 30 TO 35
PERCENT COVERAGE OF TARGETS IN AREA OF INTEREST. GP-1
T O P S E C R E T